

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Semi-Annual	<b>Date:</b> 12/20/2022	<b>Time:</b> 8:47 AM	
<b>Name of School Corporation:</b> RIVER FOREST COMM. SCHOOL CORP	<b>Corp ID:</b> 454590		
<b>Address of School Corporation:</b> 3250 Michigan St			
<b>City:</b> Hobart	<b>Zip:</b> 46342	<b>County Number:</b> 45	
<b>VIN:</b> 4DRBUAAN49B127621	<b>License Number:</b> 32149	<b>Bus Number:</b> 16	
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2008	<b>Make of Chassis:</b> IC Corporation	<b>Year:</b> 2009
<b>Bus Type:</b> C	<b>Mileage:</b> 116369		
<b>Inspection Status:</b> R	<b>Inspected By:</b> Tim Grayson	<b>PE:</b> 7558	

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
62-1-2	One (1) taillight or one (1) brake light does not function
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
43-1-11	See Notes: Any defect inspector deems a violation not listed

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**