

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	12/20/2022	Time:	8:47 AM		
Name of School Corporation:	RIVER FOREST COMM. SCHOOL CORP			Corp ID:	454590		
Address of School Corporation:	3250 Michigan St						
City:	Hobart	Zip:	46342	County Number:	45		
VIN:	4DRBUAAN49B127621		License Number:	32149	Bus Number:	16	
Make of Body:	IC Corporation	Year:	2008	Make of Chassis:	IC Corporation	Year:	2009
Bus Type:	C			Mileage:	116369		
Inspection Status:	R	Inspected By:	Tim Grayson	PE:	7558		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
62-1-2	One (1) taillight or one (1) brake light does not function
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
43-1-11	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.