

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	12/20/2022	Time:	9:28 AM
Name of School Corporation:	NORTHERN WELLS COMM. SCHOOLS			Corp ID:	908435
Address of School Corporation:					
City:		Zip:		County Number:	90
VIN:	AT88T4C2681294216	License Number:	20446	Bus Number:	21
Make of Body:	Thomas Built Buses, Inc.	Year:	2006	Make of Chassis:	Thomas Built Buses, Inc.
Bus Type:	D	Mileage:	230596	Year:	2007
Inspection Status:	O	Inspected By:	Steve Spallinger	PE:	6921

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
40-1-2	Any required instrument or gauge is inoperative. (Speedometer, Odometer, Fuel Gauge, High beam, Brake indicator light or gauge, air pressure gauge, brake warning light, DEF Gauge)
82-1-2	See Notes: Any defect inspector deems a violation not listed
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
32-2-1	There is fuel leaking from any point on in the fuel system

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus,

behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.