## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection Date: 1/24/2023 Time: 8:40 AM

Name of School Corporation: RISING-SUN OHIO COUNTY COMM.

**Corp ID:** 586080

Address of School Corporation: 110 Henrietta St

City:Rising SunZip:47040County Number:58VIN:4DRBUAAN5DB183351License Number:3822Bus Number:5Make of Body:IC Corporation Year:2012Make of Chassis:IC Corporation Year:2013

Bus Type: C Mileage: 61793

Inspection Status: O Inspected By: Chris Clark PE: 6665

**Violations - Rejected** 

**Inspection Code Description** 

**Violations - Out of Service** 

Inspection Code Description

There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.