

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Re-Inspection	<b>Date:</b> 2/1/2023	<b>Time:</b> 12:49 PM	
<b>Name of School Corporation:</b> CLAY COMMUNITY SCHOOLS		<b>Corp ID:</b> 111125	
<b>Address of School Corporation:</b> PO Box 169			
<b>City:</b> Knightsville	<b>Zip:</b> 47857	<b>County Number:</b> 11	
<b>VIN:</b> 1BAKJCPA7HF329044	<b>License Number:</b> 12552	<b>Bus Number:</b> 32	
<b>Make of Body:</b> Blue Bird Corporation	<b>Year:</b> 2016	<b>Make of Chassis:</b> Blue Bird Corporation	<b>Year:</b> 2017
<b>Bus Type:</b> C	<b>Mileage:</b> 100077		
<b>Inspection Status:</b> O	<b>Inspected By:</b> Byron Goodman	<b>PE:</b> 7008	

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
40-1-3	See Notes: Any defect inspector deems a violation not listed
15-1-2	A defroster motor is inoperative at any speed

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
64-2-1	Any rear turn signal does not function properly
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**