

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|-------------------------------|------------------------|----------|-------------------------|--------------|
| Type of Inspection: | Registration | Date: | 2/3/2023 | Time: | 10:05 AM |
| Name of School Corporation: | ELWOOD COMMUNITY SCHOOL CORP. | Corp ID: | 485280 | | |
| Address of School Corporation: | 1306 N Anderson St | | | | |
| City: | Elwood | Zip: | 46036 | County Number: | 48 |
| VIN: | 1FDXE45PX60825548 | License Number: | ECSA5 | Bus Number: | A5 |
| Make of Body: | Thomas Built Buses, Inc. | Year: | 2006 | Make of Chassis: | Ford |
| Bus Type: | A2 | Year: | 2006 | | |
| Inspection Status: | R | Mileage: | 104740 | Inspected By: | Jeremy Mason |
| | | PE: | 8139 | | |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 70-1-9 | If the words "EMERGENCY EXIT" does not appear on the top or bottom of the window or directly above each emergency exit window on the inside of the bus |
| 28-1-4 | The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction. |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.