

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	2/3/2023	Time:	12:27 PM
Name of School Corporation:	AUXILIO SERVICES (MUNCIE)			Corp ID:	251807
Address of School Corporation:	11260 Cornell Park Dr Suite 700				
City:	Cincinnati	Zip:	45242	County Number:	18
VIN:	4UZABRDT4HCJD4275	License Number:	B534N	Bus Number:	M27
Make of Body:	Thomas Built Buses, Inc.	Year:	2018	Make of Chassis:	Thomas Built Buses, Inc.
Bus Type:	C	Mileage:	51758	Year:	2017
Inspection Status:	O	Inspected By:	Steve Spallinger	PE:	6921

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
30-1-1	There are any holes in the floor
22-1-1	A dripping oil or fluid leak
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
35-1-1	A heater motor is not operating properly
89-1-3	The strobe light is inoperative

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
51-2-1	The service door does not open or close properly

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.