

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	2/13/2023	Time:	12:19 PM		
Name of School Corporation:	RICHLAND-BEAN BLOSSOM C.S.CORP			Corp ID:	535705		
Address of School Corporation:	600 S Edgewood Dr						
City:	Ellettsville	Zip:	47429	County Number:	53		
VIN:	4DRBUC8N1LB047797		License Number:	23438	Bus Number:	21	
Make of Body:	IC Corporation	Year:	2019	Make of Chassis:	IC Corporation	Year:	2019
Bus Type:	C			Mileage:	29458		
Inspection Status:	O	Inspected By:	Byron Goodman	PE:	7008		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
2-1-3	Any back-up light lens is cracked, broken, faded or missing
62-1-1	Any lens is cracked, missing, faded or of the wrong color
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
64-1-2	A lens is cracked, missing or wrong color
20-1-2	Excessive effort is needed to open the emergency door
20-1-5	Door glass is chipped, or cracked

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
4-2-1	Any body clamp is broken or missing
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
24-2-2	Any body surface protrudes beyond the normal limits of the body structure
20-2-4	Emergency door is not securely fastened to body
31-2-1	Frame is deteriorated, cracked, broken or severely bent
11-2-2	A bumper does not meet manufactures specifications
70-2-1	Any glass or glazing is broken through or missing

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.