

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Re-Inspection      **Date:** 2/16/2023      **Time:** 9:47 AM  
**Name of School Corporation:** DECATUR COUNTY COMM. SCHOOL      **Corp ID:** 161655  
**Address of School Corporation:** 1645 W SR 46  
**City:** Greensburg      **Zip:** 47240      **County Number:** 16  
**VIN:** 1FDWE35P56HA37750      **License Number:** 69468      **Bus Number:** ND2  
**Make of Body:** Ford      **Year:** 2005      **Make of Chassis:** Ford      **Year:** 2006  
**Bus Type:** A2      **Mileage:** 135804  
**Inspection Status:** O      **Inspected By:** Chris Clark      **PE:** 6665

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>   |
|------------------------|--|
| 20-1-8                 | If bus manufactured after 5-2-1994, positive door opening device is missing or fails to operate properly |
| 66-1-2                 | Any emergency device is in poor condition  |
| 24-1-1                 | The bus body has rust or rusted through areas which may weaken the body                                  |

### Violations - Out of Service

Inspection Code      Description

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.