

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Registration	Date: 2/17/2023	Time: 9:48 AM
Name of School Corporation: AUXILIO SERVICES (MUNCIE)		Corp ID: 251807
Address of School Corporation: 11260 Cornell Park Dr Suite 700		
City: Cincinnati	Zip: 45242	County Number: 18
VIN: 1BAKGCEA1MF368630	License Number: 719433D	Bus Number: M47
Make of Body: Blue Bird Corporation	Year: 2019	Make of Chassis: Blue Bird Corporation
Year: 2022		
Bus Type: C	Mileage: 36213	
Inspection Status: R	Inspected By: Steve Spallinger	PE: 6921

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
22-1-1	A dripping oil or fluid leak
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.