REPORT OF SCHOOL BUS INSPECTION

Type of 9:48 Time: Registration Date: 2/17/2023 Inspection: AM **AUXILIO SERVICES (MUNCIE)** 251807 Name of School Corporation: Corp ID: **Address of School Corporation:** 11260 Cornell Park Dr Suite 700 County City: Cincinnati Zip: 45242 18 Number: License VIN: 1BAKGCEA1MF368630 719433D Bus Number: M47 Number: Make of Blue Bird Blue Bird Make of Body: Year: 2019 Year: 2022 Corporation Chassis: Corporation Bus Type: С Mileage: 36213 Inspection Inspected PE: R Steve Spallinger 6921 Status: By:

Violations - Rejected

<u>inspection</u>	<u>Description</u>
Code	

22-1-1 A dripping oil or fluid leak

The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

Violations - Out of Service

<u>Inspection Code</u> <u>Description</u>

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.