## REPORT OF SCHOOL BUS INSPECTION

Type of 10:09 Time: Post-Crash Inspection Date: 2/17/2023 Inspection: AM Name of School Corporation: AUXILIO SERVICES (MUNCIE) Corp ID: 251807 **Address of School Corporation:** 11260 Cornell Park Dr Suite 700 County City: Cincinnati Zip: 45242 18 Number: License VIN: 4UZABRFC9LCLJ5477 B718T **Bus Number:** M45 Number: Make of Thomas Built Buses, Year: 2020 Make of Body: Freightliner Year: 2018 Chassis: Inc. **Bus Type:** С Mileage: 25669 Inspection Inspected О PE: Steve Spallinger 6921 Status: By:

## **Violations - Rejected**

<u>Inspection Code</u> <u>Description</u>

89-1-3 The strobe light is inoperative

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.