REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		Date:	2/22/2023	Time:	9:41 AM
Name of School Corporation:	HUM	AN SERVICES	INC. HEAD STAR	Т	Corp ID:	03003Z
Address of School	Corporation:	PO Box 119				
City:	Clifford	Zip:	47203		County Number:	3
VIN:	1GB3G3BG3D	1149429	License Number:	5934	Bus Number:	1012
Make of Body:	Chevrolet Year	: 2013	Make of Chassis:	Blue Bird Corporation	Year:	2013
Bus Type:	С		Mileage:	90767		
Inspection Status:	А	Inspected By:	Seth Davidson		PE:	8101

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.