

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	2/22/2023	Time:	11:31 AM
Name of School Corporation:	AUXILIO SERVICES (MUNCIE)	Corp ID:	251807		
Address of School Corporation:	11260 Cornell Park Dr Suite 700				
City:	Cincinnati	Zip:	45242	County Number:	18
VIN:	4DRBUC8P9JB524152	License Number:	B486N	Bus Number:	M7
Make of Body:	IC Corporation	Year:	2016	Make of Chassis:	IC Corporation
Year:		Year:		Year:	2018
Bus Type:	C	Mileage:	56543	PE:	6921
Inspection Status:	O	Inspected By:	Steve Spallinger		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
64-1-4	Any front turn signal does not function properly
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
40-1-2	Any required instrument or gauge is inoperative. (Speedometer, Odometer, Fuel Gauge, High beam, Brake indicator light or gauge, air pressure gauge, brake warning light, DEF Gauge)

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
8-2-1	There is no brake certification, or the certification has expired or is not signed

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.