

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	2/21/2023	<b>Time:</b>	8:06 AM
<b>Name of School Corporation:</b>	JAC-CEN-DEL COMM. SCHOOL CORP.			<b>Corp ID:</b>	696900
<b>Address of School Corporation:</b>	723 N Buckeye St				
<b>City:</b>	Osgood	<b>Zip:</b>	47037	<b>County Number:</b>	69
<b>VIN:</b>	4UZABRFB3MCMP1541	<b>License Number:</b>		<b>Bus Number:</b>	9
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2020	<b>Make of Chassis:</b>	Thomas Built Buses, Inc.
<b>Bus Type:</b>	C	<b>Mileage:</b>	18218	<b>Year:</b>	2021
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Chris Clark	<b>PE:</b>	6665

### Violations - Rejected

#### Inspection Code Description

### Violations - Out of Service

#### Inspection Code

#### Description

7-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).
-------	--

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**