

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date:** 2/21/2023 **Time:** 1:19 PM
Name of School Corporation: NORTH CENTRAL PARKE COMM SCH CORP **Corp ID:** 616375
Address of School Corporation: 1497 E STATE RD 47
City: MARSHALL **Zip:** 47859 **County Number:** 61
VIN: 1GB3G2BG1E1162465 **License Number:** 170817 **Bus Number:** PH2
Make of Body: Chevrolet **Year:** 2014 **Make of Chassis:** Chevrolet **Year:** 2014
Bus Type: **Mileage:** 147621
Inspection Status: O **Inspected By:** Byron Goodman **PE:** 7008

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description