

REPORT OF SCHOOL BUS INSPECTION

| | | | | | | | |
|---------------------------------------|--------------------------|------------------------|------------------|-------------------------|--------------------------|--------------|------|
| Type of Inspection: | Annual | Date: | 2/27/2023 | Time: | 10:20 AM | | |
| Name of School Corporation: | JAY SCHOOL CORPORATION | | | Corp ID: | 383945 | | |
| Address of School Corporation: | PO Box 1239 | | | | | | |
| City: | Portland | Zip: | 47371 | County Number: | 38 | | |
| VIN: | 4UZABRDU4DCFA4615 | License Number: | 4296 | Bus Number: | 80 | | |
| Make of Body: | Thomas Built Buses, Inc. | Year: | 2012 | Make of Chassis: | Thomas Built Buses, Inc. | Year: | 2013 |
| Bus Type: | C | Mileage: | 155705 | | | | |
| Inspection Status: | R | Inspected By: | Steve Spallinger | PE: | 6921 | | |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 50-1-2 | The seat belt cutter is not secured using a positive fastening method. |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.