

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 2/28/2023	Time: 8:57 AM	
Name of School Corporation: PAOLI COMMUNITY SCHOOL CORP.	Corp ID: 596155		
Address of School Corporation: 501 S Elm St			
City: Paoli	Zip: 47454	County Number: 59	
VIN: 4UZABRDD78CZ10900	License Number: B207Q	Bus Number: 11	
Make of Body: Freightliner	Year: 2007	Make of Chassis: Freightliner	Year: 2008
Bus Type: C	Mileage: 173804		
Inspection Status: R	Inspected By: Philip Lubbers	PE: 7703	

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
70-1-7	Any emergency window is too difficult to open
63-1-4	Any rear tire has less than 2/32 inch tread depth when measured in any two adjacent major grooves

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.