## REPORT OF SCHOOL BUS INSPECTION

Type of 9:49 Time: Annual Date: 2/28/2023 Inspection: AM Name of School Corporation: PAOLI COMMUNITY SCHOOL CORP. Corp ID: 596155 **Address of School Corporation:** 501 S Elm St County City: Paoli Zip: 47454 59 Number: License VIN: 1BAKFCPH68F253248 B764F **Bus Number:** 10 Number: Make of Blue Bird Blue Bird Year: 2007 Make of Body: Year: 2008 Corporation Chassis: Corporation **Bus Type:** С Mileage: 158361 Inspection Inspected

Philip Lubbers

PE:

7703

## **Violations - Rejected**

Status:

R

## **Inspection Code Description**

46-1-5 Upholstery or padding is ripped, torn, or improperly repaired Any back-up light lens is cracked, broken, faded or missing 2-1-3

By:

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.