

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	3/1/2023	Time:	11:30 AM		
Name of School Corporation:	CLAY COMMUNITY SCHOOLS	Corp ID:	111125				
Address of School Corporation:	PO Box 169						
City:	Knightsville	Zip:	47857	County Number:	11		
VIN:	4DRBUC8NXNB202902	License Number:	25000	Bus Number:	70		
Make of Body:	IC Corporation	Year:	2021	Make of Chassis:	IC Corporation	Year:	2022
Bus Type:	C	Mileage:	24802				
Inspection Status:	O	Inspected By:	Byron Goodman	PE:	7008		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
64-2-1	Any rear turn signal does not function properly

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.