

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 3/2/2023 **Time:** 12:56 PM
Name of School Corporation: NORTH PUTNAM COMMUNITY SCHOOLS **Corp ID:** 676715
Address of School Corporation: Box 169
City: Bainbridge **Zip:** 46105 **County Number:** 67
VIN: 1HA6GUB70MN011267 **License Number:** NEW1267 **Bus Number:** A3
Make of Body: Endera **Year:** 2021 **Make of Chassis:** Chevrolet **Year:** 2022
Bus Type: A1 **Mileage:** 36396
Inspection Status: O **Inspected By:** Byron Goodman **PE:** 7008

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.