REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	**Date:**	3/2/2023	**Time:**	12:56 PM
Name of School Corporation:	NORTH PUTNAM COMMUNITY SCHOOLS			**Corp ID:**	676715
Address of School Corporation:	Box 169				
City:	Bainbridge	**Zip:**	46105	**County Number:**	67
VIN:	1HA6GUB70MN011267	**License Number:**	NEW1267	**Bus Number:**	A3
Make of Body:	Endera **Year:** 2021	**Make of Chassis:**	Chevrolet	**Year:**	2022
Bus Type:	A1	**Mileage:**	36396		
Inspection Status:	O	**Inspected By:**	Byron Goodman	**PE:**	7008

Violations - Rejected

Inspection Code	Description
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**