REPORT OF SCHOOL BUS INSPECTION

| Type of Inspection: | Re-Inspection | | Date: | 3/2/2023 | Time: | 1:01 PM |
|---------------------|--------------------|---------------|------------------|-----------|-----------------------|---------|
| Name of School Cor | poration: NOR | TH PUTNAM CO | OMMUNITY SCHO | OLS | Corp ID: | 676715 |
| Address of School C | orporation: | Box 169 | | | | |
| City: | Bainbridge | Zip: | 46105 | | County Number: | 67 |
| VIN: | 1HA6GUB71N | /N011357 | License Number: | NEW1357 | Bus Number: | A6 |
| Make of Body: | Endera Year | : 2021 | Make of Chassis: | Chevrolet | Year: | 2022 |
| Bus Type: | A1 | | Mileage: | 21762 | | |
| Inspection Status: | А | Inspected By: | Byron Goodman | | PE: | 7008 |

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.