

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual **Date:** 3/6/2023 **Time:** 10:27 AM
Name of School Corporation: NORTH LAWRENCE COMM. SCHOOLS **Corp ID:** 475075
Address of School Corporation: 595 Stars Blvd
City: Bedford **Zip:** 47421 **County Number:** 47
VIN: 1GB3GSBG3L1259177 **License Number:** 91515 **Bus Number:** V43
Make of Body: Chevrolet **Year:** 2020 **Make of Chassis:** Chevrolet **Year:** 2020
Bus Type: **Mileage:** 17673
Inspection Status: A **Inspected By:** Seth Davidson **PE:** 8101

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description