## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 3/7/2023 Time: 9:19 AM Name of School Corporation: NORTH DAVIESS CO. COMM. SCHOOL Corp ID: 141375

**Address of School Corporation:** 5494 E SR 58

City:ElnoraZip:47529County Number:14VIN:4DRBUAAP0AB184999License Number:Bus Number:6Make of Body:IC Corporation Year:2010Make of Chassis:IC Corporation Year:2010

Bus Type: A1 Mileage: 190242

Inspection Status: O Inspected By: Philip Lubbers PE: 7703

## Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

57-1-5 Step-well light is missing or inoperative

## **Violations - Out of Service**

<u>Inspection Code</u> <u>Description</u>

Warning lights fail to operate correctly

## **Bus Type Description**

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.