

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 3/7/2023	Time: 9:19 AM
Name of School Corporation: NORTH DAVIESS CO. COMM. SCHOOL	Corp ID: 141375	
Address of School Corporation: 5494 E SR 58		
City: Elhora	Zip: 47529	County Number: 14
VIN: 4DRBUAAP0AB184999	License Number: B208E	Bus Number: 6
Make of Body: IC Corporation	Year: 2010	Make of Chassis: IC Corporation
Year: 2010	Bus Type: A1	Mileage: 190242
Inspection Status: O	Inspected By: Philip Lubbers	PE: 7703

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
57-1-5	Step-well light is missing or inoperative

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
65-2-1	Warning lights fail to operate correctly

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**