

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	3/7/2023	Time:	10:16 AM		
Name of School Corporation:	VIGO COUNTY SCHOOL CORPORATION			Corp ID:	848030		
Address of School Corporation:	3250 Maple Ave						
City:	Terre Haute	Zip:	47804	County Number:	84		
VIN:	4DRBUC8N4HB691303		License Number:	12450	Bus Number:	1696	
Make of Body:	IC Corporation	Year:	2016	Make of Chassis:	IC Corporation	Year:	2017
Bus Type:	C			Mileage:	104938		
Inspection Status:	O	Inspected By:	Byron Goodman	PE:	7008		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
51-1-1	Any door seals are missing, damaged, or torn
70-1-4	There is any cracked glass to the immediate right or left of the driver

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)(Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district).
51-2-1	The service door does not open or close properly
70-2-2	Any glass or glazing is cracked, chipped, clouded or distorted badly enough to prohibit a clear view from within the bus

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.