

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	3/7/2023	Time:	10:25 AM
Name of School Corporation:	VIGO COUNTY SCHOOL CORPORATION			Corp ID:	848030
Address of School Corporation:	3250 Maple Ave				
City:	Terre Haute	Zip:	47804	County Number:	84
VIN:	4DRBUAAN6CB623723	License Number:	2138	Bus Number:	1182
Make of Body:	IC Corporation	Year:	2011	Make of Chassis:	IC Corporation
		Year:		Year:	2012
Bus Type:	C	Mileage:	106579		
Inspection Status:	O	Inspected By:	Byron Goodman	PE:	7008

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
14-1-1	See Notes: Any defect inspector deems a violation not listed
34-1-1	Any headlight is inoperative
64-1-1	Turn signals are not properly mounted
64-1-4	Any front turn signal does not function properly
33-1-1	The grill has any exposed edges that may cause injury
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
11-1-1	The front bumper does not extend to the edge of the fenders

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
11-2-2	A bumper does not meet manufactures specifications

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.