

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	3/9/2023	Time:	9:02 AM
Name of School Corporation:	OLDENBURG ACADEMY			Corp ID:	69D135
Address of School Corporation:	PO Box 200				
City:	Oldenburg	Zip:	47036	County Number:	69
VIN:	1GB3G2BG0E1119932			License Number:	B821N
Make of Body:	Collins Bus Corporation	Year:	2014	Make of Chassis:	Chevrolet
Bus Type:	A2			Year:	2014
Inspection Status:	O	Inspected By:	Chris Clark	PE:	6665

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-5	Any hanger, clamp or bracket is missing, loose or broken

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.