

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 3/9/2023	<b>Time:</b> 9:46 AM
<b>Name of School Corporation:</b> CANAAN COMMUNITY ACADEMY	<b>Corp ID:</b> 9725	
<b>Address of School Corporation:</b> 8775 N. Canaan Main St.		
<b>City:</b> Canaan	<b>Zip:</b> 47224	<b>County Number:</b> 39
<b>VIN:</b> 1BAKF CPA1CF286895	<b>License Number:</b> 23187	<b>Bus Number:</b> 19
<b>Make of Body:</b> Blue Bird Corporation	<b>Year:</b> 2011	<b>Make of Chassis:</b> Blue Bird Corporation
<b>Year:</b> 2012	<b>Bus Type:</b> C	<b>Mileage:</b> 137467
<b>Inspection Status:</b> O	<b>Inspected By:</b> Troy Boyd	<b>PE:</b> 5171

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
34-1-1	Any headlight is inoperative
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
64-1-4	Any front turn signal does not function properly

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94
62-2-1	Two (2) or more taillights or brake lights do not function (LED lights are considered non-functional if 50% or more pixels are inoperable in one light.)
64-2-1	Any rear turn signal does not function properly

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**