

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual **Date:** 3/13/2023 **Time:** 11:52 AM
Name of School Corporation: PERU COMMUNITY SCHOOLS **Corp ID:** 525635
Address of School Corporation: 35 W 3rd St
City: Peru **Zip:** 46970 **County Number:** 52
VIN: 1GB6G3AGXA1168294 **License Number:** 83999 **Bus Number:** Tiger2
Make of Body: Starcraft **Year:** 2010 **Make of Chassis:** Chevrolet **Year:** 2010
Bus Type: A2 **Mileage:** 120696
Inspection Status: R **Inspected By:** Randy McPike **PE:** 7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.
12-1-6	The re-set switch is not of a push button type, requires a key, or has an override (bypass) capability.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**