

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	3/16/2023	<b>Time:</b>	10:58 AM
<b>Name of School Corporation:</b>	MANCHESTER COMMUNITY SCHOOLS			<b>Corp ID:</b>	858045
<b>Address of School Corporation:</b>	PO Box 308				
<b>City:</b>	North Manchester	<b>Zip:</b>	46962	<b>County Number:</b>	85
<b>VIN:</b>	4UZABRFD8LCLW0872	<b>License Number:</b>	23186	<b>Bus Number:</b>	5
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2019	<b>Make of Chassis:</b>	Freightliner
<b>Bus Type:</b>	C	<b>Mileage:</b>	83453	<b>Year:</b>	2020
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Randy McPike	<b>PE:</b>	7018

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
52-1-1	There are any loose, broken, or missing mountings
44-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative
95-1-10	Does not move smoothly or rest solidly on the ground

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**