REPORT OF SCHOOL BUS INSPECTION

Type of 10:41 Time: Annual Date: 3/16/2023 Inspection: AM CRAWFORDSVILLE COMM. SCHOOLS 545855 Name of School Corporation: Corp ID: **Address of School Corporation:** 1000 Fairview Ave County City: Crawfordsville Zip: 47933 54 Number: License VIN: 1T7YT4A2791111513 32513 Bus Number: 19 Number: Thomas Built Buses, Year: 2008 Thomas Built Buses, Year: Make of Make of Body: 2009 Chassis: Inc. **Bus Type:** D Mileage: 116684 Inspection Inspected PE: 0 Nate King 7421 Status: By:

Violations - Rejected

Inspection Code Description

17-1-1 Any dome light is inoperative

Violations - Out of Service

Inspection

Code	<u>Description</u>
	There is body damage which could cause injury to persons near the bus (e.g. jagged
24-2-1	metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the

bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type D School Bus - A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.