REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	**Date:**	3/21/2023	**Time:**	9:48 AM
Name of School Corporation:	BREMEN PUBLIC SCHOOLS			**Corp ID:**	505480
Address of School Corporation:	512 W Grant St				
City:	Breman	**Zip:**	46506	**County Number:**	50
VIN:	4UZABRDT3CCBA1277	**License Number:**	476	**Bus Number:**	2
Make of Body:	Thomas Built Buses, Inc. **Year:** 2011	**Make of Chassis:**	Freightliner	**Year:**	2012
Bus Type:	C	**Mileage:**	116726		
Inspection Status:	O	**Inspected By:**	Travis Harrold	**PE:**	8022

Violations - Rejected

Inspection Code	Description

Violations - Out of Service

Inspection Code	Description
7-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.