REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Date: 3/23/2023 Time: 10:14 AM

Name of School Corporation: BLACKFORD COUNTY SCHOOLS Corp ID: 50515

Address of School Corporation: 668 W CR 200S

City:Hartford CityZip:47348County Number:5VIN:4DRBUC8N8LB238231License Number:23578Bus Number:119

Make of Body: IC Corporation Year: 2019 Make of Chassis: IC Corporation Year: 2020

Bus Type: C Mileage: 43913

Inspection Status: R Inspected By: Steve Spallinger PE: 6921

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

7-1-3 Air leak at proper connection

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.