REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	3/28/2023	**Time:**	9:45 AM
Name of School Corporation:	HANOVER COMM. SCHOOL CORP.			**Corp ID:**	454580
Address of School Corporation:	PO Box 645				
City:	Cedar Lake	**Zip:**	46303	**County Number:**	45
VIN:	1GB3G2BG1C1196659	**License Number:**	14188	**Bus Number:**	44
Make of Body:	Star Trans **Year:** 2012	**Make of Chassis:**	Chevrolet	**Year:**	2012
Bus Type:		**Mileage:**	82742		
Inspection Status:	R	**Inspected By:**	Tim Grayson	**PE:**	7558

Violations - Rejected

Inspection Code	Description
62-1-9	LED type lights have 25% to 49% pixels inoperable in any one light

Violations - Out of Service

Inspection Code	Description

Bus Type Description