

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date:** 3/28/2023 **Time:** 9:57 AM
Name of School Corporation: HANOVER COMM. SCHOOL CORP. **Corp ID:** 454580
Address of School Corporation: PO Box 645
City: Cedar Lake **Zip:** 46303 **County Number:** 45
VIN: 1GB3G2BG1C1196659 **License Number:** 14188 **Bus Number:** 44
Make of Body: Star Trans **Year:** 2012 **Make of Chassis:** Chevrolet **Year:** 2012
Bus Type: **Mileage:** 82742
Inspection Status: A **Inspected By:** Tim Grayson **PE:** 7558

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description