

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	3/28/2023	Time:	12:40 PM		
Name of School Corporation:	NEW CASTLE COMM. SCHOOL CORP.			Corp ID:	333445		
Address of School Corporation:	236 W CR 100 S						
City:	New Castle	Zip:	47362	County Number:	33		
VIN:	4DRBWAAR7HB672322	License Number:	11733	Bus Number:	32		
Make of Body:	IC Corporation	Year:	2016	Make of Chassis:	IC Corporation	Year:	2017
Bus Type:	D	Mileage:	64347				
Inspection Status:	R	Inspected By:	Jeremy Mason	PE:	8139		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
50-1-1	The seat belt cutter is not located within the driver's view and reach
50-1-2	The seat belt cutter is not secured using a positive fastening method.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.