## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:AnnualDate:3/30/2023Time:9:59 AMName of School Corporation:RSI TRUCK & BUS REPAIR, INCCorp ID:45005Z

Address of School Corporation: 3333 Sheffield Ave

City:HammondZip:46327County Number:45VIN:4DRBUSKN99B673979License Number:Bus Number:4Make of Body:AmTranYear:2007Make of Chassis:IC CorporationYear:2009

Bus Type: C Mileage: 145332

Inspection Status: R Inspected By: Nathan Sherer PE: 7029

## Violations - Rejected

## <u>Inspection Code</u> <u>Description</u>

13-1-1 Any clearance light is missing, cracked, faded, wrong color, or inoperative

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.