REPORT OF SCHOOL BUS INSPECTION

Type of Post-Crash Inspection Date: 4/5/2023 Time: 12:48 PM

Name of School Corporation: CLAY COMMUNITY SCHOOLS Corp ID: 111125

Address of School Corporation: PO Box 169

City:KnightsvilleZip:47857County Number:11VIN:4DRBUC8N1FB520148License Number:7463Bus Number:4

Make of Body: Year: 2014 Make of Chassis: IC Corporation Year: 2015

Bus Type: C Mileage: 88395

Inspection Status: O Inspected By: Byron Goodman PE: 7008

Violations - Rejected

Inspection Code Description

The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.