REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:4/10/2023Time:9:30 AMName of School Corporation:CRAWFORD CO. COMM. SCHOOL CORPCorp ID:131300

Address of School Corporation: 5808 E Administration Rd

City:MarengoZip:47140County Number:13VIN:4DRBUAAP28B503197License Number:Bus Number:24Make of Body:IC Corporation Year:2008Make of Chassis:IC Corporation Year:2008

Bus Type: C Mileage: 157442

Inspection Status: A Inspected By: Philip Lubbers PE: 7703

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.