## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:4/11/2023Time:8:35 AMName of School Corporation:CRAWFORD CO. COMM. SCHOOL CORPCorp ID:131300

**Address of School Corporation:** 5808 E Administration Rd

City:MarengoZip:47140County Number:13VIN:4DRBUSKP5BB266216License Number:2537Bus Number:50Make of Body:IC Corporation Year:2011Make of Chassis:IC Corporation Year:2011

Bus Type: C Mileage: 105534

Inspection Status: R Inspected By: Philip Lubbers PE: 7703

## Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

The area around any warning light is not painted black

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.