REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:4/11/2023Time:8:49 AMName of School Corporation:CRAWFORD CO. COMM. SCHOOL CORPCorp ID:131300

Address of School Corporation: 5808 E Administration Rd

City:MarengoZip:47140County Number:13VIN:4DRBUC8P5HB364264License Number:6890Bus Number:56Make of Body:IC Corporation Year:2017Make of Chassis:IC Corporation Year:2017

Bus Type: C Mileage: 116799

Inspection Status: R Inspected By: Philip Lubbers PE: 7703

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

50-1-3 The seat belt cutter is contained in a compartment.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.