## REPORT OF SCHOOL BUS INSPECTION

9:05

Type of Re-Inspection Date: 4/13/2023 **Time**: Inspection: AM Name of School Corporation: SWITZERLAND COUNTY SCHOOL CORP 787775 Corp ID: **Address of School Corporation:** 1040 W Main St County City: Zip: 47043 78 Vevay Number: License VIN: 4UZABRDT9CCBL7494 B861G **Bus Number:** 39 Number:

Make of Thomas Built Buses, Year: 2012 Make of Body: Freightliner Year: 2012

Chassis:

Bus Type: Α1 Mileage: 200816

Inspected PE: **Inspection Status:** O Chris Clark 6665 By:

## Violations - Rejected

**Inspection Code Description** 

Inc.

46-1-5 Upholstery or padding is ripped, torn, or improperly repaired

## **Violations - Out of Service**

Inspection **Description** Code

Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at 7-2-4 other than a proper connection).

## **Bus Type Description**

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.