

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	4/13/2023	<b>Time:</b>	12:41 PM
<b>Name of School Corporation:</b>	HERITAGE HALL CHRISTIAN SCHOOL			<b>Corp ID:</b>	18-PS-HHC
<b>Address of School Corporation:</b>	6401 West River Road				
<b>City:</b>	Muncie	<b>Zip:</b>	47304	<b>County Number:</b>	18
<b>VIN:</b>	1HVBBPLP2NH447968	<b>License Number:</b>	B246AD	<b>Bus Number:</b>	5
<b>Make of Body:</b>	IC Corporation	<b>Year:</b>	1992	<b>Make of Chassis:</b>	IC Corporation
<b>Bus Type:</b>	C	<b>Mileage:</b>	246543	<b>Year:</b>	1992
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Steve Spallinger	<b>PE:</b>	6921

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
89-1-7	See Notes: Any defect inspector deems a violation not listed
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
35-1-1	A heater motor is not operating properly
30-1-1	There are any holes in the floor
68-1-1	Washers do not function properly in any manner

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
8-2-8	The electric power assist motor fails to operate

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**