## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			Date:	4/14/2023	Time:	8:46 AM
Name of School C	orporation:	BISH	OP NOLL INST	ΓΙΤυτΕ		Corp ID:	45B970
Address of School Corporation:		1519 Hoffman St					
City:	Hammond		Zip:	46327		County Number:	45
VIN:	1GBJG31U761117388			License Number:	B203E	Bus Number:	Α
Make of Body:	Thomas Built Buses, Inc.	Year:	2005	Make of Chassis:	Chevrolet	Year:	2005
Bus Type:	A2			Mileage:	101006		
Inspection Status:	0		Inspected By:	Tim Grayson		PE:	7558

## **Violations - Rejected**

Inspection Code	<u>Description</u>
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
37-1-1	The horn does not operate at all

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.