

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection	Date: 4/14/2023	Time: 7:14 PM	
Name of School Corporation: NORTH MONTGOMERY COMM SCH CORP	Corp ID: 545835		
Address of School Corporation: 480 W 580 N			
City: Crawfordsville	Zip: 47933	County Number: 54	
VIN: 4DRBUC8N3HB373379	License Number: 10914	Bus Number: 22	
Make of Body: IC Corporation	Year: 2015	Make of Chassis: IC Corporation	Year: 2017
Bus Type: C	Mileage: 75202		
Inspection Status: O	Inspected By: Nate King	PE: 7421	

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
11-1-1	The front bumper does not extend to the edge of the fenders
33-1-1	The grill has any exposed edges that may cause injury

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.