

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Re-Inspection	<b>Date:</b> 4/11/2023	<b>Time:</b> 11:11 AM	
<b>Name of School Corporation:</b> NETTLE CREEK SCHOOL CORP.	<b>Corp ID:</b> 898305		
<b>Address of School Corporation:</b> 795 Baker Rd			
<b>City:</b> Hagerstown	<b>Zip:</b> 47346	<b>County Number:</b> 89	
<b>VIN:</b> 4DRBUC8N8JB424154	<b>License Number:</b> 17080	<b>Bus Number:</b> 28	
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2017	<b>Make of Chassis:</b> IC Corporation	<b>Year:</b> 2018
<b>Bus Type:</b> C	<b>Mileage:</b> 89884		
<b>Inspection Status:</b> O	<b>Inspected By:</b> Jeremy Mason	<b>PE:</b> 8139	

### Violations - Rejected

#### Inspection Code Description

### Violations - Out of Service

#### Inspection Code

#### Description

7-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).
-------	--

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.