

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	4/17/2023	Time:	1:51 PM
Name of School Corporation:	AUXILIO SERVICES (MUNCIE)			Corp ID:	251807
Address of School Corporation:	11260 Cornell Park Dr Suite 700				
City:	Cincinnati	Zip:	45242	County Number:	18
VIN:	4UZABRFC7LCLJ5476	License Number:	P417560	Bus Number:	M44
Make of Body:	Freightliner	Year:	2018	Make of Chassis:	Thomas Built Buses, Inc.
Bus Type:	C	Mileage:	24371	Year:	2020
Inspection Status:	O	Inspected By:	Steve Spallinger	PE:	6921

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
52-1-1	There are any loose, broken, or missing mountings
62-1-9	LED type lights have 25% to 49% pixels inoperable in any one light
35-1-1	A heater motor is not operating properly

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.