

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	4/20/2023	Time:	10:50 AM
Name of School Corporation:	PRIMROSE WEST CARMEL			Corp ID:	1100382
Address of School Corporation: 3746 W. 96th st					
City:	Carmel	Zip:	46032	County Number:	29
VIN:	1GBHG31C181231394	License Number: B115K		Bus Number:	A1
Make of Body:	Chevrolet	Year:	2008	Make of Chassis:	Collins Bus Corporation
Bus Type:	A1	Mileage: 67860		Year:	2008
Inspection Status:	O	Inspected By:	Joel Flores	PE:	7415

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
68-1-4	See Notes: Any defect inspector deems a violation not listed
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
62-2-1	Two (2) or more taillights or brake lights do not function (LED lights are considered non-functional if 50% or more pixels are inoperable in one light.)
50-2-2	The seat belt cutter does not have a full width handgrip, with a protective blade to minimize risk

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.